


GPH13(24-48)H21A* WIRING DIAGRAM



	NuStart
1	RUN
N/C	RUN CAP
2	ACTIVE
3	START WINDING
N/C	NOT USED
4	COMMON

STANDARD AC WIRING

GPH13(24-48)H21A* WIRING DIAGRAM

