


WIRING DIAGRAM

LEGEND-EQUIPMENT DIAGRAM

- 24 V. LINE V. } FACTORY WIRING
- - - 24 V. LINE V. } FIELD WIRING
- 24 V. LINE V. } FIELD WIRING
- GROUND
- JUNCTION
- WIRE NUT OR CONNECTOR
- COIL
- CAPACITOR
- RELAY CONTACT (N.O.)
- RELAY CONTACT (N.C.)
- THERMISTOR
- INTERNAL OVERLOAD PROTECTOR
- PRESSURE ACTUATED SWITCH
- TEMP. ACTUATED SWITCH
- POL. PLUG FEMALE HOUSING (MALE TERM.)
- POL. PLUG MALE HOUSING (FEMALE TERM.)
- RESISTOR OR HEATING ELEMENT
- MOTOR WINDING
- TERMINAL
- SINGLE IN LINE CONNECTION
- TDR TIME DELAY RELAY



PRINTED FROM D15761SP04 REV A

NuStart

- 1 RUN WINDING
- 2 RUN CAP
- 3 ACTIVE
- 4 START WINDING
- 5 ON/OFF
- 6 NEUTRAL