

 Nu-Calgon

LED

NuStart™


Compressor Soft Starter

5010-20


208/230 VAC, Single Phase
50/60 Hz, 08-16A FLA/RLA

Requires a Contactor

Use Flat blade or #2 Pozzi Screwdriver.
Tightening torque
11.5 lb-in (1.3Nm)



Starts on
contactor closure



NuStart

LED Status

- Normal: No Light
- Low Voltage: 10/ sec.
- Over Current: 1/3 secs.
- Three Failed Starts: 3/3 secs.
- Cycle Delay or Fault: 1/ sec.



Scan To
Learn More



WARNING

Allow 2 minutes to
discharge run capacitor
before disconnecting



AVERTISSEMENT

Laisser 2 minutes pour décharger le
condensateur avant de déconnecter

RUN WINDING (R)

RUN CAPACITOR (RC)

ACTIVE (T2)



START WINDING (S)

COMPRESSOR COMMON (C)

NOT USED

